



Volume 19, No.7

This newsletter is a little late as my computer is in for repairs. I'm using another one that I'm unfamiliar with and my limited computer ability makes reattaching the ads from our sponsors a difficult task. To say it is frustrating is an understatement. Thanks to my wonderful daughter, all is right in the world of the ACHM Newsletter.

Last month's events, the Prairie Dog Central Fall Supper and the Fall Colour Tour in Falcon Lake were well attended and from what I heard fun was had by all. Carol and I went to the Fall Supper, the train ride was fabulous and the supper in Grosse Isle was delicious.

Many of our Club members as well as members of the Triumph Drivers Club attended the Perogy Dinner at the Lockport Church this past Sunday.

### Restoration Tip

Recently I was helping Graeme Lowden with the trafficator for his BT7 as he was replacing the wiring and I had just done one a few days before in one of the restoration project I am working on. All went well until I went to attach the wiring harness to the back of the trafficator. The colour tracers on the loom he brought were not of the same colour as original. Graeme told me that he obtained his wiring loom from Moss Motors while the one I had recently done was from British Wiring and was correct. So I contacted Moss Motors and while they were helpful in sorting out this problem, I wondered why they would sell harnesses that do not match the original wiring loom.


**THE CHROME PIT**

**PROVEN SHOW WINNER**

Unit 502  
1510 Dublin Avenue  
Winnipeg, MB R3E 3A5  
Ph. (204) 779-7131  
Fax. (204) 779-7152  
[www.thechrome-pit.com](http://www.thechrome-pit.com)

Chrome • Copper • Nickel  
Bead • Gold  
Black Chrome

**WEST CAR SERVICE**  
(1996) Ltd.  
330 Stanley St.  
(Just 3 blocks west of Higgins Ave. & Main St.)  
*Specializing in*  
**VOLVO REPAIRS**  
VEHICLE SAFETY INSPECTIONS  
**947-2656**



Later, I discussed this problem with Roger Morcilla who also had installed a new wiring loom in his BT7 and he mentioned that he had faced the same problem. So if anyone plans to replace their trafficator with a Moss one, here is the order on how to do it.

On an original wiring loom for the trafficator, when viewed from the back, going from left to right; the left wire is green/yellow, the next one is green, next one is green/blue and the last one is brown.

On the Moss one, so it works properly with your signal lights, horns etc., you must wire it as follows; left wire is green/white, next one is green/brown, next one is green/red and the last one is brown/black.

### Healey Family Tree

Those of you who, like me, live & breathe Healey's might enjoy this website <http://www.healeydata.com/> where they endeavor to keep track of every Austin Healey.

### Christmas Party

December 12<sup>th</sup> is the date, starting with cocktails at 6:30pm. We are going to the same location as last year, The Round Table. Please go to [www.roundtable.com](http://www.roundtable.com) for your choice of dinner and let Roger Morcilla know via e-mail as soon as possible so he can notify the restaurant of the number of people attending as well as the choice of meals.

### November Monthly Meeting

The November meeting will be held on November 3<sup>rd</sup> at Le Garage Café, 166 Provencher, St. Boniface, 7:30pm. The place has been totally renovated and is reopening tomorrow, Oct. 28<sup>th</sup>.

### Upcoming Events

At this time, we have no events planned for November other than our monthly meeting.



FAX (204) 943-5667      Phone (204) 943-8573

**CITY Radiator**

- RADIATORS ALL MAKES
- AIR CONDITIONING
- CUSTOM HOSES AC & PS
- GAS TANKS
- HEATERS

RUSS MARTIN      225 Princess Street  
Winnipeg, Manitoba R3B 1L5

It's time to tuck in your LBC for the winter, see you next month.

FOSTERING THE PRESERVATION  
AND DEVELOPMENT OF **CLASSIC CARS**  
AND MOTORING SPORT



**OUR PRODUCTS**

Parts for: Austin-Healey, Mini,  
MG, Triumph, Sunbeam, Jaguar.

Race Gear: Race suits, balaclava,  
race shoes, driving gloves.

Safety Equipment: window nets,  
belt systems, HANS Device, fuel cells.

**OUR SERVICES**

Engine re-building for  
BMC A, B, C-series engines.

Front suspension king pin rebuilding  
for MGB, Spridget, Big Healey.



**CLASSIC  
MOTOR  
WORKS**

10 Parrish Bay, St. Andrews, Manitoba, Canada R1A 3B2

Tel: (204) 334-2415

Toll Free: 1-800-533-9544

Fax: (204) 338-8312

Email: [classicmotorworks@shaw.ca](mailto:classicmotorworks@shaw.ca)

Website: [www.classicmotorworks.citymax.com](http://www.classicmotorworks.citymax.com)